

**Moray Offshore Windfarm (West) Limited  
Vessel Report and Contractor Report**



8460005-DBHA17-MWW-REP-000001

**MORAY OFFSHORE WINDFARM (WEST) LIMITED**

## **Vessel Report and Contractor Report**

**Document Name: 8460005-DBHA17-MWW-REP-000001**

**Revision: 4**

**Status: Final**

**Date: 15-09-2023**

# Moray Offshore Windfarm (West) Limited Vessel Report and Contractor Report



8460005-DBHA17-MWW-REP-000001

Version Control				
Revision	Date	Status	Revision Description	Distribution List
1	25-01-2023	Final	First Issue Offshore Export Cable HDD installation	MS-LOT, Moray Offshore Windfarm (West) webpage
2	15-06-2023	Final	Second Issue Scour Protection Installation	MD-LOT, Moray Offshore Windfarm (West) webpage
3	27-06-2023	Final	Third Issue Offshore Export Cable Route Clearance (Pre-lay Grapnel run)	MD-LOT, Moray Offshore Windfarm (West) webpage
4	15-09-2023	Final	Fourth Issue Windfarm array cable route clearance (PLGR) and pre-lay survey	MD-LOT, Moray Offshore Windfarm (West) webpage

## Vessel Specification and Contractors Report

This information is being provided in response to condition 3.1.3 of the Moray Offshore Windfarm (West) Limited (Moray West) Wind Farm Marine Licence (MS-00009774) and Offshore Transmission Infrastructure (OfTI) Marine Licence (MS-00009813).



*“The Licensee must ensure that at least five days prior to its engagement in the Licensed Activities, the name and function of any vessel, agent, contractor or subcontractor appointed to engage in the Works and, where applicable, the master’s name, vessel type, vessel IMO number and vessel owner or operating company are fully detailed in the Vessel Report. The Licensee must make the Vessel Reports and the Contractor Reports available on the Moray Offshore Windfarm (West) webpage: <https://www.moraywest.com/current-works/offshore-works>”*

*Any changes to the supplied details must be uploaded to the Vessel Report and the Contractor Report and the Licensing Authority must be notified, in writing, prior to any vessel, agent, contractor or sub-contractor which has not yet been notified to the Licensing Authority engaging in the Licensed Activities.*

*Only those vessels, agents, contractors or sub-contractors detailed in the Vessel Report are permitted to carry out any part of the Works”.*



Moray Offshore Windfarm (West) Limited  
Vessel Report and Contractor Report

## Vessel Specification Report



Vessel Name	Vessel Type / Function	Operator	Contact Details (Where applicable)	Vessel IMO Number	Vessel characteristics	Date on site	Relevant Marine Licence
<p>Isle of Jura</p> 	<p>Construction</p> <p>Dive Support Vessel</p>	Seafast Maritime Ltd	<p>Email: jura@seafastltd.co.uk</p> <p>Tel.mob: + 44 7936910623</p> <p>Sat Phone :+881641499304</p>	<p>IMO: 9865697</p> <p>MMSI 232021966</p> <p>Call Sign MFFY6</p>	<p>LOA: 33.18 m</p> <p>Beam: 14.5 m</p> <p>Draught: 2.60 m/4.90 m</p>	From 2/2/2023	OfTI Marine Licence (MS-00009813)
<p>Seafast Don</p> 	<p>Construction</p> <p>Crew Transfer Vessel</p>	Seafast Maritime Ltd	<p>Email: Don@seafastltd.co.uk</p> <p>Tel.IP: No Sat Phone</p> <p>Mobile: 07817545859</p>	<p>IMO: No IMO</p> <p>MMSI 232044406</p> <p>Call Sign MMMD6</p>	<p>LOA: 23.0 m</p> <p>Beam: 7.36 m</p> <p>Draught: 1.2 m</p>	From 2/02/2023	OfTI Marine Licence (MS-00009813)

Moray Offshore Windfarm (West) Limited  
Vessel Report and Contractor Report

8460005-DBHA17-MWW-REP-000001

Vessel Name	Vessel Type / Function	Operator	Contact Details (Where applicable)	Vessel IMO Number	Vessel characteristics	Date on site	Relevant Marine Licence
<p>Pioner</p> 	<p>Construction</p> <p>Rope handling boat</p>	<p>Seafast Maritime Ltd</p>	<p>Email: <a href="mailto:jura@seafastltd.co.uk">jura@seafastltd.co.uk</a></p> <p>Tel.IP: + 44 7936910623</p> <p>Mobile: +881641499304</p>	<p>IMO: No IMO</p>	<p>LOA: 5.30</p> <p>Beam: 2.15</p> <p>Draught: 0.30</p>	<p>2/02/2023</p>	<p>OFTI Marine Licence (MS-00009813)</p>
<p>Rockpiper</p> 	<p>Construction</p> <p>Scour protection installation</p>	<p>Boskalis</p>	<p>Email:</p> <p><a href="mailto:rockpiper-captain@boskalis.com">rockpiper-captain@boskalis.com</a></p> <p><a href="mailto:rockpiper-bridge@boskalis.com">rockpiper-bridge@boskalis.com</a></p> <p><a href="mailto:rockpiper-superint@boskalis.com">rockpiper-superint@boskalis.com</a></p> <p>Bridge Iridium: 00881677125478</p> <p>Master Vsat: +31 78 808 0262</p> <p>Superintendent: +31 78 808 0271</p>	<p>IMO : 9583861</p>	<p>LOA: 158.6m</p> <p>Beam: 36m</p> <p>Draught: max. 9.4m</p>	<p>~22/06/2023</p>	<p>OFTI Marine Licence (MS-00009813) and Wind Farm Marine Licence (MS--)</p>

Moray Offshore Windfarm (West) Limited  
Vessel Report and Contractor Report

<p>C/S Nexans Skagerrak</p> 	<p>Cable Lay Vessel</p> <p>Route Clearance (Pre-lay Grapnel Run)</p>	<p>Nexans Norway AS</p>	<p>Call Sign: LCEK          Captain Office: +47 90573814          Bridge: +47 23674602          Iridium: +88 1677131813          NxN Offshore Manager: +47 907 78 429          E-mail: <a href="mailto:master@nexans-skagerrak.osm.no">master@nexans-skagerrak.osm.no</a></p>	<p>IMO: 7619458</p>	<p>DP2</p> <p>Flag: Norwegian (NOR)</p> <p>Length LOA = 118.25m</p> <p>Breadth (mould) = 32.15m</p> <p>Draught (max.) = 5.4m</p> <p>Gross Tonnage = 8460Te</p> <p>Net Tonnage = 2539Te</p>	<p>~08.07.23 to ~20.07.23</p>	<p>OfTI Marine Licence (MS-00009813)</p>
<p>Seaway Aimery</p> 	<p>Cable Lay Vessel</p> <p>Route Clearance (Pre-lay Grapnel Run)</p> <p>Pre-lay survey (ROV)</p>	<p>Seaway 7</p>	<p>Call Sign: MDB02          Captain Office: +47 2278 5360          Bridge: +47 2278 5367          Satellite: +870 773 923 656          SW7 Offshore Manager: +47 2278 5371          E-mail: <a href="mailto:seawayaimery.captain@subsea7.com">seawayaimery.captain@subsea7.com</a></p>	<p>IMO: 9694737</p>	<p>Flag country: UK</p> <p>DP system: DP2</p> <p>LOA: 95 m</p> <p>Breadth: 21.5 m</p> <p>Depth: 8.8 m</p> <p>Max operating draft: 7.2 m</p> <p>Gross tonnage: 8,530 t</p> <p>Dead weight tonnage: 4,700 t</p>	<p>~21.09.23 to 21.10.23</p>	<p>Wind Farm Marine Licence (MS-00009774)</p>

**Moray Offshore Windfarm (West) Limited**  
**Vessel Report and Contractor Report**



8460005-DBHA17-MWW-REP-000001

**Wind Farm Marine Licence – List of Contractors and Subcontractors**

Activity	Contractor Details					Subcontractor Details				
	Contractor Name	Address	Contact Name	Role(s) on project	Contact Number	Contractor Name	Address	Contact Name	Role(s) on the Project	Contact Number
Scour Protection Installation	Boskalis	Rosmolenweg 20, 3356LK, Papendrecht, The Netherlands	[REDACTED]	Works Manager Scour Protection	[REDACTED]					
			[REDACTED]	Project Manager	[REDACTED]					
Array cable PLGR and Pre-lay survey works	Seaway 7	Seaway 7, Prospect Road, Arnhall Business Park, Westhill, Aberdeenshire, AB32 6FE, United Kingdom	[REDACTED]	Project Ops Manager	[REDACTED]					
			[REDACTED]	Project Director	[REDACTED]					



OfTI Marine Licence – List of Contractors and Subcontractors

Activity	Contractor Details					Subcontractor Details				
	Contractor Name	Address	Contact Name	Role(s) on project	Contact Number	Contractor Name	Address	Contact Name	Role(s) on the Project	Contact Number
Offshore Export Cable HDD installation	Nexans	Nexans Subsea & Land Systems BG 11 Alva Street, Edinburgh, EH2 4PH, UK	[REDACTED]	Offshore Site Manager	[REDACTED]	Caldive Limited	18 High St, Invergordon IV18 OET	[REDACTED]	Managing Director	[REDACTED]
Scour Protection Installation	Boskalis	Rosmolenweg 20, 3356LK, Papendrecht, The Netherlands	[REDACTED]	Works Manager Scour Protection  Project Manager	[REDACTED]					
Offshore Export Cable(s) Route Clearance (Pre-lay Grapnel Run)	Nexans Norway AS	Nexans Norway AS Freserveien 1, 0196 Oslo, Norway	[REDACTED]	Project Manager  Deputy Project Manager	[REDACTED]					