

# Notice to Mariners

## Array cable routes – Fall pipe recovery from Subsea - July 2024

Moray West Offshore Wind Farm

<b>Issue date</b>	3-Jul-24
<b>Version</b>	01
<b>Activity</b>	Array cable route D05– Fall pipe recovery lift

## Revision History

<b>Version</b>	<b>Issue Date</b>	<b>Status</b>	<b>Updates</b>
01	03-Jul-24	Final	First Issue

# 1. Introduction

This notice to mariners is to inform that Moray Offshore Windfarm (West) Limited (Moray West) will be carrying out fall pipe recovery work from the vessel North Sea Enabler on the Moray West Offshore Wind Farm site.

Fall Pipe was previously dropped by the Heimdal R, reported on 17<sup>th</sup> June 2024.

The Moray West site is located on the Smith Bank in the Outer Moray Firth, approximately 22.5km from the Caithness coastline. The offshore wind farm site covers an area of approximately 225km<sup>2</sup>. The offshore wind farm site is given in Figure 1 below.




Figure 1. Moray West Wind Farm Site. Location of the cable routes for the works

The vessel works are to take place within the D05 500m zone, D05 is circled in red in above figure 1.

The North Sea Enabler is expected to arrive on site on 3<sup>rd</sup> July 2024. Work duration is expected to be approximately 4 days

## 2. Fallpipe recovery works

Scope of work includes subsea lifting of a dropped rock installation fallpipe, subsea cutting and recovery to deck at location D05

The work will be performed by the North Sea Enabler

The coordinates of the work site boundary are presented in the below Table 1 (these are the same as presented in Figure 1 above):

Windfarm Site Boundary Coordinates				
Site ID	UTM30(N) Easting (m)	UTM30(N) Northing (m)	WGS84 Latitude	WGS84 Longitude
1	505117	6436040	58° 3.946' N	2° 54.796' W
2	507845	6438790	58° 5.426' N	2° 52.017' W
3	509247	6441560	58° 6.918' N	2° 50.583' W
4	509828	6445010	58° 8.780' N	2° 49.983' W
5	509362	6448300	58° 10.551' N	2° 50.450' W
6	508444	6450480	58° 11.729' N	2° 51.382' W
7	507377	6452080	58° 12.588' N	2° 52.468' W
8	506584	6451400	58° 12.223' N	2° 53.279' W
9	504067	6448160	58° 10.482' N	2° 55.851' W
10	500728	6445090	58° 8.825' N	2° 59.258' W
11	496301	6442410	58° 7.380' N	3° 3.768' W
12	491909	6440620	58° 6.413' N	3° 8.237' W
13	489705	6437070	58° 4.496' N	3° 10.472' W
14	487142	6433650	58° 2.650' N	3° 13.068' W
15	487208	6429170	58° 0.237' N	3° 12.986' W

Table 1. Coordinates of wind farm site boundaries.

## 3. General Safety Advice

Please be aware that, during the subsea lifting and recovery works by virtue of its mode of operation the North Sea Enabler will be Restricted in her Ability to Manoeuvre (RAM) and will also display the appropriate day shapes while conducting cable installation operations are taking place as defined under COLREGs (International Regulations for Preventing Collisions at Sea 1972, Rule 3).

Masters of approaching vessels are therefore requested to maintain their vessels and gears at a minimum safe passing distance from the vessel of 500 metres when it is undertaking work and showing the appropriate shapes and lights in accordance with COLREGs Rule 27 to not compromise the safety of the 'North Sea Enabler' and their crew, and the ability to undertake its contracted works.

## 4. Vessel Information

The Fall pipe recovery will be undertaken by the North Sea Enabler.

Details are provided in table 2 below.

<b>Vessel Name</b>	North Sea Enabler
<b>MMSI Number</b>	314627000
<b>Operating Company</b>	North Sea Shipping
<b>Vessel Call Sign</b>	8PBK2
<b>Vessel Phone Number</b>	+19024185705 / +870773252407
<b>Vessel Email Address</b>	bridge.enabler@northsea.no

Table 2. Vessel 'North Sea Enabler' - General Information



Figure 2. North Sea Enabler – photo of the vessel (Formerly Horizon Enabler)

## 5. Developer Contacts Details

Enquiries regarding the contents of this Notice to Mariners should be directed to Moray West team (contact details below).

For fisheries related matters, please contact the Fishery Manager, using the contact details provided below:

### Array cable - Package manager

Neil Crawford – Array cable package manager  
Address: 144 Morrison St., Edinburgh, EH3 8EX  
Email: [neil.crawford@oceanwinds.com](mailto:neil.crawford@oceanwinds.com)  
Tel : +44 7917452602

### Consenting

Moray West Development Team  
Address: 144 Morrison St., Edinburgh, EH3 8EX  
Email: [development@moraywest.com](mailto:development@moraywest.com)  
Tel: +44 (0) 131 556 7602

### Health, Safety and Other Matters

Richard Pargeter (Head of HSSE)  
Address: 144 Morrison St., Edinburgh, EH3 8EX  
Email: [richard.pargeter@oceanwinds.com](mailto:richard.pargeter@oceanwinds.com)  
Tel: +44 (0) 1315 567602

### Fishing Enquiries

Iain McMyn (Fishery Manager)  
Address: 144 Morrison St., Edinburgh, EH3 8EX  
Email: [Iain.McMyn@oceanwinds.com](mailto:Iain.McMyn@oceanwinds.com)  
Tel: +44 (0) 7780 191088

Alex Winrow-Giffin, Brown and May Marine (Company Fisheries Liaison Officer)  
Email: [alex@brownmay.com](mailto:alex@brownmay.com)  
Tel: +44 (0) 7760 160039

### Moray East Marine Coordination

Marine Coordination	Contact
Marine Coordinator – Duty	+44 (0) 7774 663504 <a href="mailto:mcc@moraywest.com">mcc@moraywest.com</a>
Call sign – Moray West Traffic	VTS CH16 & CH87